


FUSION FS10/FS20 Firmware Change Log		 <b>GERMAN LIGHT PRODUCTS</b>
Date:	February 18, 2022	

Main changes from 1032 to 1034		February 18, 2022
IMPROVEMENT	Updated Pixel Dimming when running in Pixel Mode	
BUG FIXES	<ul style="list-style-type: none"> <li>• Corrected Pattern Processing</li> <li>• Showing Correct Version number via RDM</li> <li>• Fixture timer was not working correctly</li> </ul>	
UPDATE PROCESS	<p><b>Fusion Stick FS10:</b>  <b>1 file have to be updated in sequence via DMX/RS485 for FS10:</b></p> <p>1. FUSN_XLR_FS10_V1034.FSN via Fusion Updater Cable and PC Software</p> <p><b>Fusion Stick FS20:</b>  <b>1 file have to be updated in sequence via DMX/RS485 for FS10:</b></p> <p>1. FUSN_XLR_FS20_V1034.FSN via Fusion Updater Cable and PC Software</p> <p><b>Fixtures can be updated daisy chain via DMX. Please make sure that no other DMX receivers or consoles are active on the line</b></p>	
INFO	Update is not show critical	