


GLP D3Prog Firmware Change Log		 GERMAN LIGHT PRODUCTS
Date:	June 22, 2022	

Main changes from V42 to V49 and pa6.12 to pa6.21		2022-06-22
FEATURES	This firmware combination allows to work on windows 11 systems	
BUG FIXES	Solved: preliminary software release versions (below V 1.0, e.g. 0.11.4) are displayed correctly	
UPDATE PROCESS	<p>Programmers running V42 can be updated with the update function of the pa software to V49 if a bootloader V3 is installed, already. The bootloader version can be checked in the special menu of the d*prog.</p> <p>If this bootloader is not installed the bootloader has to be updated ISP, first, with a second D*Prog.</p>	
Further Information	We suggest to store the executable programmer application V6.21 in a folder together with the ftdi driver, ftd2xx.dll. Usually no further action is needed. Just in case, you can install the driver manually, or execute the CDM21228_Setup file from FTDI	
Main changes from V40 to V42 and pa6.XX to pa6.12		2019-10-30
FEATURES	<ul style="list-style-type: none"> This firmware allows to update all kind of D*Progs in the market to the same software level V42 (except the very first versions without display) Added an option to choose between 16 or 4 memories via pa software version 612 This is most important for D2Prog and DProg as they have less memory. 	
BUG FIXES	<ul style="list-style-type: none"> Improved English pa version translation 	

UPDATE PROCESS	<p>Programmers can be updated with the update function of the pa software if a bootloader V3 is installed, already. The bootloader version can be checked in the special menu of the d*prog.</p> <p>If this bootloader is not installed the bootloader has to be updated ISP, first, with a second D*Prog.</p>
----------------	--