

GLP Firmware Change Log



Fusion X-PAR 12Z / Firmware Log / 05/08/2023

Below you will find the history of all fixture firmware versions since the release of the device. Please note the respective information on functional changes, extensions, optimizations, etc. Even if it is our goal to develop firmware updates without relevant performance changes, it can always happen that optimizations or bug fixes can affect the device performance. Please read the note on "INFO" as a matter of urgency.

We strongly advise that firmware updates be carried out on individual replacement devices first.

Likewise, updates should never be carried out shortly before an important use of the device. If in doubt, speak to your GLP Service Team.

- [08 May 2023 / Main changes from V1.0.02 to V1.0.10](#)
- [07 Sep 2020 / First Fieldtest Firmware V1.0.02](#)

08 May 2023 / Main changes from V1.0.02 to V1.0.10	
FEATURES	<ul style="list-style-type: none">• improved dimmer curves• improved color wheel• added dimmer snap function• optimized manual control (e.g. removed 16 bit channels etc)• Improved RDM (included Factory Backup) Caution !! Factory Backup will restore all settings to default including DMX-Address and DMX-Mode !!• Rearranged the display menus as to the latest specifications• Renamed some display entrys as to the latest specifications• DMX Hold is the default setting for No DMX
BUG FIXES	<ul style="list-style-type: none">• RDM Discovery was sometimes not working via MA2
UPDATE PROCESS	<ul style="list-style-type: none">• Update via Fusion PC Software with USB to XLR Adapter or update with Fusion Upater (for ExoSeries and XParSeries)
VERSION DETAILS	<ul style="list-style-type: none">• XP12_MAIN_1_V01.GFS
INFO	<ul style="list-style-type: none">• As dimming curves changed and bug in color wheel is fixed the fixtures will not be show compatible• Added RDM Factory backup! One click can change Start Address and DMX Mode !!
07 Sep 2020 / First Fieldtest Firmware V1.0.02	
Info	First Fieldtest Firmware

No responsibility taken for misprints, errors and technical changes.

Technical data is subject to change without notice as a result of product modification.

GLP German Light Products GmbH, Industriestrasse 2, 76307 Karlsbad, Germany, Managing Director: Udo Künzler